## Light is OSRAM



15 January 2021

## Product Or Individual Q-Code Discontinuation (acc. JEDEC J-STD-048) OS-PDN-2021-005

Last order:	28 February 2021
Last delivery:	31 May 2021



Please direct your feedback to your local Sales office.



DISCONTINUED				NEW (REPLACEMENT)		
Device	Ordering Code	Brand	Reason for discontinuation	Device	Datasheet Ordering Code	Brand
SPL BF98-40-5-12B	all					
SPL BF98-40-5-12B (964,5 +/-2NM)	Q65112A9059	Laser Bar	Phase out of product due to reduced	no replacement		
SPL BF98-40-5-12B (965,2 +/-2NM)	Q65112A9836	Laser Bar	Phase out of product due to reduced	no replacement		
SPL BF98-40-5-12B (966,5 +/-2NM)	Q65112A9060	Laser Bar	Phase out of product due to reduced	no replacement		
SPL BF98-40-5-12B (969 +/-3NM)	Q65112A8145	Laser Bar	Phase out of product due to reduced	no replacement		
SPL BF98-40-5-12B (969,3 +/-2NM)	Q65112A8144	Laser Bar	Phase out of product due to reduced	no replacement		
SPL BF98-40-5-12B (970,3 +/-2NM)	Q65112A9510	Laser Bar	Phase out of product due to reduced	no replacement		
SPL BY98-15-34-00C	all					
SPL BY98-15-34-00C (972 +/-3NM)	Q65112A7825	Laser Bar	Phase out of product due to reduced	no replacement		
SPL EJ91-40-8-20D	all					
SPL EJ91-40-8-20D (908+/-5NM)	Q65112A7935	Laser Bar	Change to improved Chiptype with higher power	SPL EJ91-40-8-30D (908.0 +/-5NM)	Q65113A0375	Laser Bar
SPL EJ91-40-8-20D (909+/-5NM)	Q65112A7937	Laser Bar	Change to improved Chiptype with higher power	no replacement		

