## **Panasonic**



## **Product Discontinuation Notice: S35H Series Connectors**

PDN.PG01.05.18.2020 05.18.2020

| Effective Date:          | Immediate  |  |
|--------------------------|--|--|
| Last Time Buy Date:      | March 31, 202 <mark>1</mark>   |  |
| Last Eligible Ship Date: | June 6, 2021   |  |
| Discontinuation Details: | The S35H Series Connectors are being discontinued due to lack of demand. |  |
| Suggested Replacement:   | See Attached.  |  |
| Affected Part Numbers:   | See Attached.  |  |
| Datasheets:              | See Attached.  |  |
| Notes:                   |  |  |

## Panasonic PDN.PG01.05.18.2020 Affected Parts

| Affected Series | Affected Part Numbers | Suggested Replacement Series | Suggested Replacement Part Numbers |
|-----------------|-----------------------|------------------------------|------------------------------------|
| S35H            | AXF5B3412             | None                         | None                               |
| S35H            | AXF5B4012             | None                         | None                               |
| S35H            | AXF5B5012             | None                         | None                               |
| S35H            | AXF5B6012             | None                         | None                               |
| S35H            | AXF6B3412             | None                         | None                               |
| S35H            | AXF6B4012             | None                         | None                               |
| S35H            | AXF6B5012             | None                         | None                               |
| S35H            | AXF6B6012             | None                         | None                               |